

Save As PDF, high quality lines, 600 DPI

File location: C:\pdmdata\PDM\FREE HAND GUARD\SOLIDWORKS FILES\
Tapped Hole Layout

R2.743

3X $\varnothing$ #7 DRILL (.201) THRU
1/4-20 UNC THRU

